EDGE/ACE Joining Instructions for Continuous Run Fixtures

PLEASE READ ALL INSTRUCTIONS CAREFULLY BEFORE INSTALLING. RISK OF FIRE AND ELECTRICAL SHOCK. FIXTURE MUST BE INSTALLED BY A QUALIFIED ELECTRICIAN. ALL INSTALLS SHOULD BE IN ACCORDANCE WITH NATIONAL, LOCAL BUILDING AND ELECTIRCAL CODES. ALL WIRES AND MATERIALS USED FOR INPUT/OUTPUT MUST BE UL APPROVED.

IMPORTANT NOTE: DO NOT DRILL THROUGH SIDE OF FIXTURE TO SECURE TO TBAR. DRILLING THROUGH SIDE OF FIXTURE COULD RESULT IN DRILLING INTO LED BOARD, VOIDING ARON WARRANTY

ARON[™]

Light Delivered

Fixture Joining Steps:





 3
 Remove Joiner Screw and place to the side



IMPORTANT NOTE: DO NOT DRILL THROUGH SIDE OF FIXTURE TO SECURE TO TBAR. DRILLING THROUGH SIDE OF FIXTURE COULD RESULT IN DRILLING INTO LED BOARD, VOIDING ARON WARRANTY



Designed and Manufactured in the USA www.aronlighting.com

EDGE/ACE Joining Instructions for Continuous Run Fixtures





Insert joiner screw through male L bracket and thread into female L bracket.



6 Tighten screw to pull fixtures tight together DO NOT overtighten joiner screw.







fixture, encasing wires.

COORDINATE INSTALL WITH CEILING CONTRACTOR

REFER TO SHOP DRAWINGS FOR CONFIGURATIONS

ARON